

Keurig coffeemakers can spray scalding water



13 hours ago

[\(0\) Comments](#)

Keurig coffeemakers can spray scalding water

Details: Keurig MINI Plus Brewing System with model number K10 (previously identified as model number B31). Recalled brewers have an identification number starting with “31” followed by a range of numbers printed on a white sticker on the bottom of the brewer. They are single-serve, hot beverage brewers and were sold in 13 different colors with silver trim. Recalled units were sold between December 2009 and December 2014. They can be identified by the serial number printed on a white sticker on the bottom of the brewer. Serial numbers involved in the recall can be found at <http://www.cpsc.gov/en/Recalls/2015/Keurig-Recalls-MINI-Plus-Brewing-Systems/>

Why: Water can overheat during brewing, spray out and burn consumers.

Incidents: Keurig has received about 200 reports of hot liquid escaping from the brewer, including 90 reports of burn-related injuries.

How many: About 6.6 million in the U.S. and 564,000 in Canada.

For more: Call Keurig Green Mountain at 844-255-7886 Monday through Friday from 8 a.m. to 8 p.m. ET, and from 8 a.m. to 3 p.m. ET on Saturday or Sunday or visit www.keurig.com and click on “Recall Info.”

— The Associated Press

Copyright 2015 The Southern. All rights reserved. This material may not be published, broadcast, rewritten or redistributed.
